

Czargon's Tri-Intersecting Torus


Install & Assembly Instructions by Percy Echols II

web: percyechols.com email: mail@percyechols.com ph: 412-345-3943



1. Place the Base on a flat and secure surface

- Use both hands when handling the **Base**
- Leave it UNPLUGGED from outlet




ON (recieve power)



OFF (No power)

2. Make sure the Power Button is OFF

- When being handled the **Power Button** may be pressed (recessed)



3. Gently place Plasma Lamp into the Base

- Use both hands when handling the **Plasma Lamp**.
- Make sure there is not thing obstructing the socket or blocking the copper mesh in the **socket**.
- The **Plasma Lamp** is designed to sit securely in the **socket**.



4. Plug your power cord into a Grounded Outlet

- For safe operation make sure the **outlet** is grounded



5. Turn ON Piece by pressing the Power Button

- Do NOT leave Plasma Light Sculpture unattended
- if displayed in exhibition space, please use a motion sensor.



6. Display, Dim the Lights, and Admire

- Best viewed in Dim Lighting
- Do NOT leave Lamp unattended
- ***Warning those with Surgical Medical Devices are advise to not touch the artwork and stay min of 3ft from the artwork as it could interfere and cause discomfort.***
- Signage is advised



7. Turn OFF when not in use

- see ***Plasma Light Sculpture - Owner's Guide*** for more information on Safety Tips and Cleaning.